

IMPORTANT PRODUCT NOTICE
Types G105, F190 and F191
Date of Manufacture: September 2004 to October 2004

(Personalize with complete company name and address)

(Personalize with name of contact at company)

Dear *(Personalize)*:

Our records indicate that you have received a Fisher Type G105, F190 or F191 manufactured in September 2004 or October 2004.

Background

We have discovered that the male NPT threads on the valves may not be fully machined. The picture attached below shows the difference between a valve with correct threads and one with the incorrect partial threads. While the partial threads do not constitute a safety hazard, a valve with the partial threads may not seal properly with the coupling threads due to lack of make-up threads.

Action Required by You

Locate and inspect any G105, F191 or F190 shipped to you in September or October of 2004 for the partially machined threads. If you have any units with the partially machined threads remove them and replace them. Utilize your local Fisher LP Equipment distributor for ordering no-charge replacement units.

Description of Product Affected

<u>Order #</u>	<u>Item #</u>	<u>Customer Order #</u>	<u>Qty</u>	<u>Description</u>	<u>Date</u>
<i>(USE CUSTOMER ORDER DATA TO COMPLETE THIS INFORMATION)</i>					

Thank you for your assistance.

(Fisher Distributor Contact)

cc: Curtis Bagby, Fisher Controls

